


### Minimum plooi afstand



tot lengte	0,5	0,8	1	1,5	2	3	4	5	6	8	10	12	15	20
500	3.5	3.5	4	5	6	10	13	18	19	32	65	65	95	100
500-1000	4	4	4	5	6	10	13	18	20	32	65	65	100	100
1000-2000	4.5	4.5	4.5	5.5	7	12	15.5	19	26	32	65	65(max l = 1750 !)	xxx	xxx
2000-2500	5	5	5	6	7.5	12.5	16	20	30	39	65	xxx	xxx	xxx
2500-3000	5	5	5	6	7.5	12.5	16	20	30	65	xxx	xxx	xxx	xxx
3000-4000	5.5	5.5	5.5	6.5	10	15	17	22	39	xxx	xxx	xxx	xxx	xxx

### Minimum plooi afstand z-profiel



tot lengte	0,5	0,8	1	1,5	2	3	4	5	6	8	10	12	15
500	6	6	6	7	7	16	16	25	25	40	72	72	110
500-1000	6	6	6	7	7	16	16	25	25	40	72	72	110
1000-2000	6	6	6	7	7	16	16	25	25	40	72	72(max l = 1750 !)	xxx
2000-2500	6	6	6	7	9	16	16	30	40	40	72	xxx	xxx
2500-3000	6	6	6	9	9	16	20	30	40	40	xxx	xxx	xxx
3000-4000	6	6	6	9	9	16	20	30	40	xxx	xxx	xxx	xxx